ENVIRONMENTAL CHEMISTS

Analysis For Total Metals By EPA Method 200.8

M07343 Client ID: 07/07/11 Date Received: Date Extracted: 07/08/11 Date Analyzed: 07/08/11 Matrix: Water Units: ug/L (ppb)

Project: Lab ID: Data File:

Alaskan Copper Works Metro Self Monitor PO M07343

107063-01 x10 107063-01 x10.058

Instrument: ICPMS1 Operator: AP

Lower

Upper Limit:

Internal Standard: Germanium

% Recovery: 80

Limit: 60

125

Concentration Analyte: ug/L (ppb)

Chromium 541 Nickel 541 Copper 364 Zinc 113

ENVIRONMENTAL CHEMISTS

Client:

Project:

Analysis For Total Metals By EPA Method 200.8

Client ID: Method Blank Date Received: Not Applicable Date Extracted: 07/08/11 Date Analyzed: 07/08/11 Matrix: Water Units: ug/L (ppb)

Lab ID: I1-465 mb Data File: I1-465 mb.044 Instrument: ICPMS1 Operator: AP

Alaskan Copper Works

Metro Self Monitor PO M07343

125

Lower UpperInternal Standard: % Recovery: Limit: Limit: Germanium 92 60

Concentration Analyte: ug/L (ppb) Chromium <1 Nickel <1 ${\bf Copper}$ <1 Zinc <1

ENVIRONMENTAL CHEMISTS

Date of Report: 07/13/11 Date Received: 07/07/11

Project: Metro Self Monitor PO M07343, F&BI 107063

QUALITY ASSURANCE RESULTS FOR THE ANALYSIS OF WATER SAMPLES FOR TOTAL METALS USING EPA METHOD 200.8

Laboratory Code: 107047-01 (Matrix Spike)

				Percent	Percent		
	Reporting	Spike	Sample	Recovery	Recovery	Acceptance	RPD
Analyte	Units	Level	Result	MS	MSD	Criteria	(Limit 20)
Chromium	ug/L (ppb)	20	<1	113	110	67-132	3
Nickel	ug/L (ppb)	20	3.43	108	104	73-119	4
Copper	ug/L (ppb)	20	79.4	106 b	94 b	50-144	12 b
Zinc	ug/L (ppb)	50	221	113 b	99 b	46-148	13 b

Laboratory Code: Laboratory Control Sample

	Percent										
	Reporting	Spike	Recovery	Acceptance							
Analyte	Units	Level	LCS	Criteria							
Chromium	ug/L (ppb)	20	113	66-135							
Nickel	ug/L (ppb)	20	114	67-134							
Copper	ug/L (ppb)	20	112	66-134							
Zinc	ug/L (ppb)	50	114	57-135							

ENVIRONMENTAL CHEMISTS

Data Qualifiers & Definitions

- a The analyte was detected at a level less than five times the reporting limit. The RPD results may not provide reliable information on the variability of the analysis.
- A1 More than one compound of similar molecule structure was identified with equal probability.
- b · The analyte was spiked at a level that was less than five times that present in the sample. Matrix spike recoveries may not be meaningful.
- ca The calibration results for this range fell outside of acceptance criteria. The value reported is an estimate.
- c The presence of the analyte indicated may be due to carryover from previous sample injections.
- d The sample was diluted. Detection limits may be raised due to dilution.
- ds The sample was diluted. Detection limits are raised due to dilution and surrogate recoveries may not be meaningful.
- dy Insufficient sample was available to achieve normal reporting limits and limits are raised accordingly.
- fb Analyte present in the blank and the sample.
- fc The compound is a common laboratory and field contaminant.
- hr The sample and duplicate were reextracted and reanalyzed. RPD results were still outside of control limits. The variability is attributed to sample inhomogeneity.
- ht Analysis performed outside the method or client-specified holding time requirement.
- ip Recovery fell outside of normal control limits. Compounds in the sample matrix interfered with the quantitation of the analyte.
- j The result is below normal reporting limits. The value reported is an estimate.
- J The internal standard associated with the analyte is out of control limits. The reported concentration is an estimate.
- jl The analyte result in the laboratory control sample is out of control limits. The reported concentration should be considered an estimate.
- jr The rpd result in laboratory control sample associated with the analyte is out of control limits. The reported concentration should be considered an estimate.
- js The surrogate associated with the analyte is out of control limits. The reported concentration should be considered an estimate.
- lc The presence of the compound indicated is likely due to laboratory contamination.
- L The reported concentration was generated from a library search.
- nm The analyte was not detected in one or more of the duplicate analyses. Therefore, calculation of the RPD is not applicable.
- pc The sample was received in a container not approved by the method. The value reported should be considered an estimate.
- pr The sample was received with incorrect preservation. The value reported should be considered an estimate.
- ve Estimated concentration calculated for an analyte response above the valid instrument calibration range. A dilution is required to obtain an accurate quantification of the analyte.
- vo The value reported fell outside the control limits established for this analyte.
- x The sample chromatographic pattern does not resemble the fuel standard used for quantitation.

107063		13	SA	MPLE CHA	IN OF C	US'	TOI	DY	1	4 f)	71	7	11/		<i></i>	9	1.					
Send Report To DERZUO / Hompoon				SAMPLERS	(signoture)				- P. P. P.							age #		OUND TIME					
Company ALABRAU COPPER Works Address 628 S. HADER ST City, State, ZIP SEATTLE WA 98134 Phone # 206-571-6033 Fax # 206-382-4308				PROJECT NAME/NO. PO# METRO SELE MIONTEN MO7343							3	Standard (2 Weeks) RUSH Rush charges authorized by:											
				REMARKS SAMPLE DISPOSAL Dispose after 30 days Return samples Will call with instructions											ays								
Thone w	rax#	3 4 2	7301				=		- 1							can v	Vith Insti	ructions					
	-					ANALYSES REG				EEQ!	SOESLED												
Sample ID	Lab ID	Date	Time	Sample Type	# of containers	TPH-Diesel	TPH-Gasoline	BTEX by 80211	VOCs by 8260	SVOCs by 8270	HFS	OR CL 1/2 2~					1	Notes					
M 07343	01	7/4/11	12:30	1/20	/					1													
																	Y Y						
									1														
Friedman & Bruya, Inc.		r Chrame			DDYM							00	MDA	NIX) 4 MD]	mi) m					
3012 16th Avenue West	SIGNATURE Reliminished by			PRINT NAME COM									DATE 7 _{7/11}	TIME 130pm									
Seattle, WA 98119-2029 Ph. (206) 285-8282	Received by:	40/	HONG NGMAN FR					27	7/7/			17/11	ν										
Fox (206) 283-5044 FORMS\COC\COC.DOC	Received by:											0.	0 00 01	lae -	noi.	- b.a.	23	90					

ENVIRONMENTAL CHEMISTS

James E. Bruya, Ph.D. Charlene Morrow, M.S. Yelena Aravkina, M.S. Bradley T. Benson, B.S. Kurt Johnson, B.S. 3012 16th Avenue West Seattle, WA 98119-2029 TEL: (206) 285-8282 FAX: (206) 283-5044 e-mail: fbi@isomedia.com

July 13, 2011

Gerald Thompson, Project Manager Alaskan Copper Works 628 South Hanford Seattle, WA 98134

Dear Mr. Thompson:

Included are the results from the testing of material submitted on July 7, 2011 from the Metro Self Monitor PO M07343, F&BI 107063 project. There are 4 pages included in this report. Any samples that may remain are currently scheduled for disposal in 30 days. If you would like us to return your samples or arrange for long term storage at our offices, please contact us as soon as possible.

We appreciate this opportunity to be of service to you and hope you will call if you have any questions.

Sincerely,

FRIEDMAN & BRUYA. INC.

Michael Erdahl Project Manager

Enclosures ACU0713R.DOC